


0070 -

*Inging*  
8/18/2015 

**From:** "Hardy, Russell" <RussellHardy@consolenergy.com>  
**To:** "Hardy, Russell" <RussellHardy@consolenergy.com>, <pamgrubaughlittig@uta...  
**Date:** 8/17/2007 1:29 PM  
**Subject:** Emery Subsidence Report  
**Attachments:** Emery Subsidence 8-17-07.pdf

**CC:** <karlhouskeeper@utah.gov>, <waynewestern@utah.gov>, <SteveChristensen@ut...  
Please find attached the subsidence report for July .

Russell Hardy  
CONSOL ENERGY  
Phone: (435) 286-3513  
Fax: (435) 286-3516  
email: russellhardy@consolenergy.com

## **Consolidation Coal Emery Mine Subsidence Report for July 2007**

- 7-6-07 Over 14th West noticed more little cracks on the hill to the North of the main road across the field. PB
- 7-9-07 No real noticeable changes over Panel 14 West. Walked panel with Greg Hasenfus, Doug White, Randy Stockdale, Russell Hardy, Buck Parrish and Matt Hyita. Took more GPS readings of the existing cracks. PB
- 7-16-07 Walked over Panel 14 West and more little cracks over the mined area. Some of the cracks seem to be getting bigger. PB
- 7-26-07 No real noticeable change over Panel 14 West. PB
- 8-2-07 No real noticeable change over Panel 14 West. Spring has been mostly undermined and is still flowing (picture below). PB, RH



8-10-07        Nothing noticeably new over Panel 14 West. PB

8-17-07        Walked over Panel 14 West and most of the older cracks are filling in and becoming small indentations in the ground. New cracks approx.  $\frac{1}{2}$ " –  $\frac{3}{4}$ " wide are forming over the recently pillared area. RH

Footnote: During the reporting period we were developing rooms off of Panel 14 West for 1 week. The other two weeks we were on miners vacation and no mining occurred during this period. This is why we have had very little activity over Panel 14 West. RH